

Town of Whitby Conlin Rd. Garrad Rd. Intersection

Via E-Mail

June 23, 2026

Good morning, Tara,

In follow up to our April 2025 submission regarding the regarding the Conlin / Garrard corridor upgrades, our safe cycling concerns with this project continue to unfold.

Noting the north west corner guard rail, which we identified as a cycling hazard and was heavily damaged in a collision May 2025, the guard rail has once again been severely damaged as a result of a new collision.

Please reference the attached photo's taken Saturday June 20, 2026 and the May 2025 past incident.

Given the repeat occurrences with this guardrail design, and the hazard to both cyclists and pedestrians with no escape route, our request remains to have this structure removed in the interest of safety.


Happy to meet on site at your convenience to discuss possible solutions.

Respectfully,

Ron

Ron Lalonde
Executive Director
Durham Region Cycling Coalition
www.durhamsafecycling.ca

June 2026



May 2025

